The Trail Inventory of Desert NWR Las Vegas, NV





Prepared By: Federal Highway Administration Central Federal Lands Highway Division January, 2012



TABLE OF CONTENTS

<u>SECTION</u>		<u>PAGE</u>
I.	TRAIL AND TRAIL FEATURE SUMMARIES	1 - 1
II.	TRAIL LOCATION MAPS	2 - 1
III.	TRAIL IDENTIFICATION LIST	3 - 1
IV.	TRAIL CONDITION RATING SHEETS	4 - 1
V.	TRAIL DEFICIENCY RATING SHEETS	5 - 1
VI.	PHOTOGRAPHIC SHEETS	6 - 1
VII.	GLOSSARY	i

Desert NWR

Trail and Trail Feature Summaries

Trail Miles and Percentages by Surface Type and Condition

Trail Surface	Excel	lent	Total	
Туре	Miles	%	Miles	
Native	0.86	100%	0.86	
Total	0.86	100%	0.86	

Trail Miles and Percentages by Trail Classification and Condition

Trail	Excelle	ent	Total	
Classification	Miles	%	Miles	
тсз	0.86	100%	0.86	
Total	0.86	<mark>100%</mark>	0.86	

^{*}Admin Roads are included in the inventory but are not rated for condition.

Trail Features


Trail Number	Feature Type	Quantity	Grouped Feature	Milepost	Photo
T300	Sign	11	Yes	0.00	DESE_C2_107 7
T300	Bridge -sf	10	No	0.00	DESE_C2_195 2
T300	Sign	2	No	0.00	DESE_C2_195
T300	Trailhead	1	No	0.00	DESE_C2_195 0
T300	Sign	1	No	0.01	DESE_C2_195
T300	Culvert -If	20	No	0.02	
T300	Step: Rock -each	2	No	0.09	
T300	Step: Rock -each	1	No	0.12	
T300	Other	1	No	0.18	
T300	Sign	2	No	0.18	DESE_C2_195 4
T300	Bench	1	No	0.20	
T300	Bench	1	No	0.22	
T300	Sign	1	No	0.33	DESE_C2_195 5
T300	Begin Section	1	No	0.34	DESE_C2_195
T300	Sign	1	No	0.40	DESE_C2_195 7
T301	Trailhead	1	No	0.00	DESE_C2_107 8
T301	Step: Log -each	11	No	0.18	DESE_C2_107
T301	Bridge -sf	16	No	0.20	DESE_C2_108
T301	Bridge -sf	16	No	0.20	DESE_C2_108 0
T302	Trailhead	1	No	0.00	DESE_C2_108

sf - square feet

If - linear feet

cf - cubic feet

Desert NWR Trail Location Map




Trails ID

Station Name: Desert NWR Org Code: 84555

Trail Number	Trail Name	Surface Type	SAMMS	Trail Mileage	Trail Description (Begin and End point of trail)
T300	Interpretive Nature Trail	Native	10005304	0.42	From Visitor Center Parking (Rte 900) to End of Trail Loop
T301	Bird Song Trail	Native	N/A	0.37	From Corn Creek Field Station Rd. to Corn Creek Field Station Rd.
T302	Whispering Benn	Native	N/A	0.07	From Yet to be Built Trail to End of Trail

TRAIL CONDITION



	0.05		0	0.05	0.	1	0.1	Miles
	Excellent	G o	od Fair		Poor	Very Poo	or 💮	Admin Road
<u> </u>	Begin Section		Check Dam		Step Feature	\boxtimes	Gate	A N
	Trailhead		Retaining Wall		Max. Grade	\succ	Bridge	W E
Ŕτ	Trail Sign	1	Raised Trail Structure	₩	Min. Width	7/\	Bench	Š
	Drainage Structure		Water Bar	+	Intersection	×	Other	Station Boundary

Trail Name: Interpretive Nature Trail Refuge Name: Desert NWR **Trail Number:** T300 Region: 8


Section Number 001 002 Section Length (miles) 0.34 0.08 10005304 10005304 SAMMS Number 01/17/2007 01/17/2007 Rating Date **Trail Section Information** TC3 TC3 Trail Class Native Native Surface Type Surface Firmness Hard Hard Width (inches) 36 36 Average Grade (%) 4.6 4.6 Average X-slope (%) 3.80 3.80 Trail Condition Information Deferred Maintenance \$26,661 \$6,272 CRV 0.00 0.00 FCI Excellent Excellent Condition

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$32,932	0.00	Excellent

Total Length: 0.42 Miles

TRAIL CONDITION



Trail Name:Bird Song TrailRefuge Name:Desert NWRTrail Number:T301Region: 8Total Length:0.37 Miles

Intersection

Station Boundary

Water Bar

Section Number	001
Section Length (miles)	0.37
SAMMS Number	N/A
Rating Date	08/30/2011
Trail Section Information	
Trail Class	TC3
Surface Type	Native
Surface Firmness	Firm
Width (inches)	24
Average Grade (%)	4.6
Average X-slope (%)	2.30
Trail Condition Information	
Deferred Maintenance	
CRV	\$19,340
FCI	0.00
Condition	Excellent

Drainage Structure

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$19,340	0.00	Excellent

TRAIL CONDITION



Trail Name: Whispering Benn Refuge Name: Desert NWR

Trail Number: T302 Region: 8 Total Length: 0.07 Miles

Se	ection Number	001
Se	ection Length (miles)	0.07
S	AMMS Number	N/A
R	ating Date	08/30/2011
Tra	il Section Information	
Tr	ail Class	TC3
Sı	urface Type	Native
Sı	urface Firmness	Firm
W	fidth (inches)	24
A	verage Grade (%)	3.5
A	verage X-slope (%)	1.20
Tra	il Condition Information	
D	eferred Maintenance	
C	RV	\$3,658
F	CI	0.00
C	ondition	Excellent

Trail Condition TOTALS

Deferred Maintenance	CRV	FCI	Condition
	\$3,658	0.00	Excellent

TRAIL DEFICIENCY

No Deficiencies

TRAIL NUMBER: T300 STATION: Desert NWR DATE: 08/30/2011




Photo # DESE_C2_1077 - MP 0.00 - Sign



Photo # DESE_C2_1950 - MP 0.00 - Trailhead

TRAIL NUMBER: T300 STATION: Desert NWR DATE: 01/17/2007



Photo # DESE_C2_1951 - MP 0.00 - Sign



Photo # DESE_C2_1952 - MP 0.00 - Bridge -sf

TRAIL NUMBER: T300 STATION: Desert NWR DATE: 01/17/2007



Photo # DESE_C2_1953 - MP 0.01 - Sign



Photo # DESE_C2_1954 - MP 0.18 - Sign

TRAIL NUMBER: T300 STATION: Desert NWR DATE: 01/17/2007



Photo # DESE_C2_1955 - MP 0.33 - Sign



Photo # DESE_C2_1956 - MP 0.34 - Begin Section

TRAIL NUMBER: T300 STATION: Desert NWR DATE: 01/17/2007



Photo # DESE_C2_1957 - MP 0.40 - Sign



Photo # DESE_C2_1078 - MP 0.00 - Trailhead

TRAIL NUMBER: T301 STATION: Desert NWR DATE: 08/30/2011



Photo # DESE_C2_1079 - MP 0.18 - Step: Log -each



Photo # DESE_C2_1080 - MP 0.20 - Bridge -sf

TRAIL NUMBER: T301 STATION: Desert NWR DATE: 08/30/2011



Photo # DESE_C2_1081 - MP 0.20 - Bridge -sf



Photo # DESE_C2_1082 - MP 0.00 - Trailhead

Glossary of Terms and Abbreviations

Acc Info Accessibility information available at trailhead.

Action Action required to correct deficiency.

Admin Road Administration Road. Admin Roads signed and

advertised as trails are included in the trail inventory but

a condition assessment is NOT done.

Alt SAMMS SAMMS number of Alternate Facility Type.

Alt Type Alternate Facility Type. Trail lies on a feature such as a

levee, dam, administrative road or bridge, which has a

separate SAMMS number.

AvgGrade The average grade of the trail (%). The average of five

measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

AvgSlope The average cross-slope of the trail (%). The average of

five measurements for trails less than two miles and ten measurements for trails equal to or greater than 2 miles.

Check Dam A small dam constructed across a drainage ditch, swale,

or channel to lower the speed of concentrated flows.

Condition Subjective rating of trail based on Facility Condition

Index (FCI):

FCI </= - .01 = Excellent FCI .02 - .05 = Good FCI .06 - .10 = Fair FCI .11 - .20 = Poor FCI > - .20 = Failed

Crib Wall Retaining wall.

Current

Replacement Value

(CRV)

The value of an asset determined by the estimated cost of

replacing it.

Def type Deficiency Type: Trail Structure, Drainage, Erosion,

Obstacle, Trail Location, Other.

Deferred

Maintenance (DM)

Maintenance that was not performed when scheduled.

i

Elem ID Unique identifier for each trail section: Org Code-Trail

Number-Section Number.

Facility

Condition Index (FCI)

DM/CRV

Grouped Features Grouped features include non-unique signs (mileposts,

interpretive signs, species identification, etc.), water bars, check dams, steps, drain and drainage dips. For any given grouped feature, a GPS point and photo are taken for the first occurrence only and the total number of features in the group are entered into the "quantity"

field of the data dictionary.

Info Type Type of accessibility information available at trailhead:

brochure, sign or other.

Item Item on which the "Action" (see above) will be

performed.

Manage Use Managed use of the trail: HIKE, BIKE, NSPC (non-

specified), PACK, POR (portage), SNOWSHOE, XSKI

(cross-country ski), OTHER.

MP Distance of a trail feature or deficiency from the

Trailhead.

Puncheon Log footbridge used in area of poor drainage.

Raised Trail Structure Boardwalk, Turnpike, Puncheon.

T Class Trail Class: I-V (see Appendix? for trail class

descriptions).

Tr Desig Trail Designation: Standard (Std), National Historic Trail

(NHT), National Recreation Trail (NRT), National

Scenic Trail (NST).

Turnpike Trail tread elevated with dirt, rock or other aggregate

from parallel side ditches and held in place by logs.